

Product Bulletin

33303A01

New Inflation Cylinder for MKII FJ Jacket

STOCKHOLM January 27, 2014

BACKGROUND

Our supplier has discontinued the 0.47 liter cylinder and valve sold to be used with the MKII FJ Jacket.

Due to this the following items are no longer available:

336921551 Cylinder Valve

336921552 Cylinder

336921600 Complete valve/cylinder unit

The Service Kit 336290318 will remain available on stock for some time.

Replacement items are:

97576-01 Complete Valve/Cylinder unit (Type 21.001.500 with 0.5 cylinder volume)

97575-01 Service Kit

Note: To perform service on the above mentioned cylinder valves it is required to have relevant service training and tools supplied by the manufacturer Scubapro.

Interspiro cannot supply tools or service training for this cylinder valve, Type 21.001.500