

Service Bulletin 33307B01 Emptying of cylinders as a preventive measure

STOCKHOLM January 31, 2014

ANNOUNCEMENT

The recommendation to regularly emptying the cylinders as a preventive measure ceases.

APPLIES TO

All Interspiro cylinders.

DESCRIPTION

Interspiro has previously recommended to empty cylinders at a regular basis, to prevent accumulation of humidity in the cylinders.

This recommendation has now been changed after analyzing the accumulated experience from many years of usage and the results from an extensive laboratory examination:

Provided that the compressor is delivering breathing air according to EN 12021, there is no need to empty the cylinders as a preventive measure.

The Discharge plug shall still be used when emptying cylinders to prevent uncontrollable airflows and eliminate the risk of hearing damages.